

## Product History - Mimik

<u>Change or occurrence</u>	<u>Date</u>	<u>Serial Number</u>
Mimik Introduced	Nov 1993	
Mimik II introduced – Main board changed from Thru-hole to Surface mount type	Dec 1994	4000
Transformer changed, also fuse rating changed.	Jan 1995	4500
Modifications to the Line Remote Out drive current. To remedy the problem (found on Mimik II only) whereby in multi-room applications, very occasionally the line remote out could not supply sufficient current to drive the other products it is connected to. <b>Upgrade available – see Mimik Line Remote Modification Procedure</b> (accessible via Linfo Website - Product Information)	Feb 1995	4747
New version of software – fixed the programming bug whereby if a sequence of tracks was programmed into the Mimik, which included a track number ending in '0' (e.g. 10, 20 etc), the Mimik would sometimes fail to follow the programmed sequence. <b>Upgrade available – see Mimik Software Upgrade Procedure</b> (accessible via Linfo Website - Product Information)	Sep 1996	7954
Single Voltage Mimik introduced – whereby the Mimik can only be used with its set mains voltage and can not be adjusted.	May 1997	10000
Double Function Keys removed from front panel.	May 1997	10429
Laser cable changed and main board modified to improve playability of poor quality or damaged CDs <b>Upgrade available – see Mimik Disc Read Modification Procedure</b> (accessible via Linfo Website - Product Information)	Dec 1997	11010
Driver IC's changed from thru-hole to surface mount type.	Aug 1998	12039
Mekk (laser mechanism) changed from MCP 812 to MCP 380 – this change had no discernable effect on performance – change was necessary due to discontinuation of MCP 812 by manufacturer	Mar 1999	13038
Mimik discontinued	May 1999	

